


# Basic Detail Report

---



## Damage to USS Intrepid's Rudder Post Casting

### Date

March 23, 1944

### Primary Maker

USS Intrepid (CV/CVA/CVS-11)

### Medium

photographic paper

### Description

Photograph, Black and white; Official horizontal image of USS Intrepid in dry dock to repair torpedo damage. This view shows the area where Intrepid's rudder is usually attached to the ship, although the rudder itself has been removed and does not appear in the image. The rudder post housing is cracked. There is a man in upper left corner wearing a helmet with a cigarette in his mouth looking at the camera. Caption on top right of image reads "Official Photograph // Not to be Released // for Publication // U.S. Naval Drydocks // Hunters Point // San Francisco, Calif." Caption on bottom left of image reads "397-44-S8 CV11 // Port side of rudder post casting showing cracks and // damage // Hunters Point 23 March 1944".

### Dimensions

8 x 10 in. (20.3 x 25.4 cm)