


Basic Detail Report



Damage and Repairs to Starboard Side Void Compartment on USS Intrepid

Date

March 28, 1944

Primary Maker

USS Intrepid (CV/CVA/CVS-11)

Medium

photographic paper

Description

Photograph, Black and white; Official horizontal image of the damage on the starboard side of void compartment (C-717-V) on USS Intrepid. Intrepid is in dry dock to repair torpedo damage. Parts of the void compartment are labeled in white marker indicating where patches and damaged are located. Labeled items include the rudder post casting, shell patch and an access hole.

Caption on top right of image reads "Official Photograph // Not to be Released // for Publication // U.S. Naval Drydocks // Hunters Point // San Francisco, Calif." Caption on bottom left of image reads "414-44-S4 CV11 // Starboard side of void compartment C-717-V, looking aft // Hunters Point 28 March 1944".

Dimensions

10 x 8 in. (25.4 x 20.3 cm)