


Basic Detail Report



Patch on the Hull of USS Intrepid after Torpedo Attack

Date

March 23, 1944

Primary Maker

USS Intrepid (CV/CVA/CVS-11)

Medium

photographic paper

Description

Photograph, Black and white; Official horizontal image of USS Intrepid in dry dock to repair torpedo damage. The view shows the starboard side of the hull near the stern. "Keep Clear // Jury Rudder" is painted in light paint on the starboard side near the stern. The rig for the jury rudder extends from the painted words down toward the bottom of the hull. To the right of the rig is a shell patch on the hull of the ship. Scaffolding surrounds the bottom of the ship. One of the ship's propellers, or screws, is visible at right. There is a man on the starboard side of the ship looking away. There are two men visible on the bottom of the dry dock next to the ship. Caption on top right of image reads "Official Photograph // Not to be Released // for Publication // U.S. Naval Drydocks // Hunters Point // San Francisco, Calif." Caption on bottom left of the image reads "404-44-S8 CV-11 // View of starboard side near stern, looking down, showing // jury rudder rig and shell patch // Hunters Point 23 March 1944".

Dimensions

8 x 10 in. (20.3 x 25.4 cm)