


Basic Detail Report



Patch on the Hull of USS Intrepid after Torpedo Attack

Date

March 23, 1944

Primary Maker

USS Intrepid (CV/CVA/CVS-11)

Medium

photographic paper

Description

Photograph, Black and white; Official horizontal image of USS Intrepid in dry dock to repair torpedo damage. The shell patch put over the hole created by a Japanese torpedo is visible on the hull of the ship. One of the ship's propellers, or screws, is visible at the bottom of the image. Caption on top right of image reads "Official Photograph // Not to be Released // for Publication // U.S. Naval Drydocks // Hunters Point // San Francisco, Calif." Caption on bottom left of image reads "403-44-58 CV-11 // View of starboard side near stern, looking aft, showing // shell patch // Hunters Point 23 March 1944".

Dimensions

8 x 10 in. (20.3 x 25.4 cm)