


Basic Detail Report



Bottom of USS Intrepid in Dry Dock

Date

March 23, 1944

Primary Maker

USS Intrepid (CV/CVA/CVS-11)

Medium

photographic paper

Description

Photograph, Black and white; Official horizontal image of the bottom of USS Intrepid in dry dock to repair torpedo damage. Wrinkles on the hull are visible. There is scaffolding at the bottom of the ship. One of the ship's propellers, or screws, can be seen at lower left. Caption on top right of image reads "Official Photograph // Not to be Released // for Publication // U.S. Naval Drydocks // Hunters Point // San Francisco, Calif." Caption on bottom left of image reads "396-44-A8 CV11 // View of port side near stern showing shell wrinkles // and jury stiffeners. // Hunters Point 23 March 1944".

Dimensions

8 x 10 in. (20.3 x 25.4 cm)